

25X1A
R
JR
B

NPIC/P&DS/D/6-1426
17 June 1966

MEMORANDUM FOR THE RECORD

KBK

SUBJECT: [REDACTED] 70mm Data Block Reader

1. Subject device was installed in TID by [REDACTED] on 6-3-66. TID obtained satisfactory operation until 6-8-66, when it began to miss low order data. EPS attempted repair, but procedures used, including suggestions by [REDACTED] did not isolate the problem. The nature of the trouble suggested a design fault.

2. [REDACTED] returned on 6-14-66 to determine the cause of the malfunction. The conclusion reached by [REDACTED] was that the metering system drive roller was not the correct diameter and resultant measuring error caused data to be missed.

3. A temporary repair was made utilizing plastic tape to increase the roller diameter. [REDACTED] will request additional contract funds to cover the fabrication and installation of a new roller.

25X1A

[REDACTED]
Equipment Performance Section, DB/P&DS

Declass Review
by NIMA/DOD